

LANPSJD100

Installation Instructions

Lankota GENERATION II Stalk Stomper® Mounting Kit for JD® 7XX0 Planters

LANKOTA®

**270 West Park Avenue
Huron, SD 57350
866-526-5682**

Numerical Parts List

Part Numbers	Description	Qty
LANPS151	Corn Planter Stalk Stomper Shoe	1
LANPSJD101	Corn Planter Stalk Stomper Mount for JD 3XX0 Planters	1
LANPSJD102	Plant Stalk Stomper Mount Shim	1
RED706K	5/8"-1 x 1.5" Carriage Bolt	2
LAN690830	5/8"-11 Serrated Flanged Nut	2

Pictorial Parts List



Preparation

1. Make sure the planter is unfolded completely.
2. Raise the planter off the ground and insert the safety stops on the cylinders.
3. Set the parking brake on the tractor.
4. Turn off the tractor engine and remove the key.

Stalk Stomper Disclaimer

Stalk Stomper Disclaimer

The most effective use of the Lankota Stalk Stomper® is achieved by adjusting the stomper pad so that when the corn head is at its normal cutting height, the pad of the shoe is 1" above the ground. Over compression of the spring can shorten the life of the stomper spring and may result in undue damage NOT covered by Lankota's Limited Warranty.


Kit Installation

Refer to the Figures

1. Remove the indicated pipe from the Wheel Pivot Mount.
2. Install the mounting bracket (LANPSJD101) onto the Wheel Pivot Mount as shown, using the existing hardware.
3. With the mount shim (LANPSJD102) between the shoe and the mounting bracket, attach the planter stomper shoe (LANPS151) to the mounting bracket with the provided carriage bolts and flange nuts.
4. Repeat these steps for each tire you desire.
5. Lower planter to running height and adjust stomper shoe chains to appropriate length.

Note: to relieve tension, lower shoe onto a block.





For further technical assistance,

Call Lankota Inc. at:

1-866-526-5682