LANSP403 Installation Instructions

Lankota Single Point Mount for John Deere 9520R, 9570R, 9620R and all 9xx0RX Tractors



Parts List


Part Numbers	Description	Qty
LANSP403W	9RX 4WD Single Point Mount	1
LANF1T2M	M20 x 60 Class 10.9 Hex Bolt	2
REDWU58	3/4" Flat Washer	2
LANFMLWO	M20 Lock Washer	2
LANSP002	Single Point 6-Port Block Spacer	4
LANSPUQHBH	Single Point Block Mounting Hardware	2
LANFJ9F2	M8 x 45mm Flanged Hex Bolt	4
LANFE01V	M8 x 30mm Socket Head Screw	4
LANFQ65N	M8 Flanged Nyloc	4
	The 3/8" hardware will not be used in this kit.	




www.lankota.com | Lankota Inc.

John Deere and JD are registered trademarks of Deere & Company. Lankota is a registered trademark of Lankota Group.

Kit Installation





Refer to Figures

- 1. Clear any dirt and debris from the indicated holes on the rear of the tractor.
- 2. Attach the mount to the tractor as shown using the M20 bolts, M20 lock washers and 3/4" flat washers.

Follow the additional instructions provided to install blocks and route hoses/fittings correctly.



For further technical assistance,

Call Lankota Inc. at:

1-866-526-5682

5/24/2019 Page | 2

www.lankota.com | Lankota Inc.

John Deere and JD are registered trademarks of Deere & Company. Lankota is a registered trademark of Lankota Group.